Home Inspection Report

35 Moreland Street Somerville, MA 02145

> Prepared for: Kevin Slattery



HIRE THE EYE OF THE TIGER™
1-800-62-TIGER

Prepared by: Frank van den Elzen, MA Lic.# 546

This report is the exclusive property of the inspection company and the client whose name appears herewith and its use by any unauthorized persons is prohibited.



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- HIRE THE EYE OF THE TIGER™ NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Report Table of Contents

Inspection Information	4
Exterior	5
Basement	8
Płumbing System	10
Electric System	12
Central Heating and Cooling	14
Kitchen and Interior Accessories	16
Bathrooms	18
Interior - Rooms	19
Attic - Ventilation - Insulation	21

Address: 35 Moreland Street, Somerville MA Page 2 of 22

TIGER HOME INSPECTION HIRE THE EYE OF THE TIGER™

Our Rating System Is As Follows:

- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
- D: Further consultation with a contractor is advised.

AN AGREEMENT

Congratulations on your expected purchasel You have made a wise decision in having your prospective home inspected. Our inspector will present you with an objective, general evaluation of the home, consistent with the professional practices and standards of the home inspection industry. To understand the report, you should read the entire document including all pre-printed and hand-written materials. Also, please read the Important Information and General Information section on each page. Each of these areas provides critical information. Please note that this inspection is limited in time and scope and not all repairs or defects may be discoverable at the time of this inspection.

Our inspectors present observations that are based on the visual examination of accessible areas of the property on the day of inspection. There is no destructive testing, probing or dismantling of any components. We cannot predict the future life expectancy or sudden failure of any component. This report is not an engineering study, or a substitute for an insurance policy, Home Warranty package, or a Manufacturer's Warranty.

You can certainly understand that we cannot see through walls, remove insulation or suspended ceiling tiles, nor enter crawl spaces that are less than 3 feet. We cannot enter attics that are not specifically designed for safe pass through. This report does not warranty the absence of wood-destroying insects. It is, however, a visual, non-destructive investigation for indications of previous or ongoing activity in readily accessible areas. Future repairs or renovations may reveal defects or wood-destroying insect activity that were not discoverable during the inspection. Tiger is not responsible for damage which is concealed or not readily accessible at the time of the inspection. If wood-destroying insect activity is discovered during the interior or exterior inspection, that activity will be documented on the report.

No evaluation has been made regarding air, soil, lead, water, waste disposal or sewage systems, asbestos, urea formaldehyde, lead paint, molds, radon, piping outside the foundation, natural or propane gas fittings or regulations, swimming pools, wood stoves, telephone systems, alarm systems or out-buildings unless otherwise noted. This report does not include the detection of rodents or general pests. We do not make an assessment of compliance with building codes. Tiger is not responsible for pointing out repairs needed to bring the home in compliance with current building codes or other regulations, and we do not report on whether the property may be lawfully used for rental, business or any other purpose.

Please be aware that only those components specifically mentioned in this report have been inspected and those components not included are not part of this report. We do not make any representation, implied or otherwise, concerning the condition of non-inspected areas. You should evaluate concerns about specific components with a qualified specialist and act upon any comments or recommendations before continuing with your purchase. It is important that you further evaluate those areas not included in this report as well as those items recorded as B, C, or NR prior to continuing on with your purchase. Tiger is not responsible for repairs on any component rated B, C, or NR. This report will not necessarily reveal all defects on the property and should not be used for negotiations. Intl.

In the event that you believe the condition of a component has not been accurately disclosed or that a particular component has been omitted from the report, it is your responsibility to notify Tiger and permit us to investigate and evaluate the situation before you make any corrective action. It is agreed that Tiger is not responsible for costs associated with repairs made prior to Tiger's investigation.

If you or anybody on your behalf chooses to initiate any type of civil action or law suit against Tiger or its inspector as a result of this inspection, in which Tiger prevails, you agree to indemnify and reimburse Tiger for its attorney fees, costs and expenses. This inspection is for your use and benefit only it may not be assigned or relied upon by any other party without written consent from Tiger. You also agree to indemnify and hold harmless Tiger for any subrogation action filed by an insurance company or any other third party as a result of this inspection.

Tiger reserves the right to retain the Inspection Report if the fee is not paid for at the time of the inspection. If the Inspector is requested to go back to the property after the inspection to check a component that was turned off, not accessible, or rated NR, there will be a \$125.00 charge.

Now that you have read and understand our Agreement and wish to proceed please sign below.

This is a duplicate of the AGREEMENT that was signed by you or your representative at the time of inspection and issued at that time.

Client: Kevin Slattery

Inspection Address: 35 Moreland Street, Somerville, MA 02145

Inspector: Frank van den Elzen, MA Lic.# 546

Inspection Date: 02/14/2015

TOTAL AMOUNT DUE: \$425.00 (Paid in Cash)

Address: 35 Moreland Street, Somerville MA
Page 3 of 22

TIGER HOME INSPECTION HIRE THE EYE OF THE TIGER™

Our Rating System Is As Follows:

A: Item is functioning as originally intended.

B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.

C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required

NR: Not Inspected, not readily accessible or not present. No rating.

D: Further consultation with a contractor is advised.

Inspection Information

Inspection Address:

35 Moreland Street

Somerville, MA 02145.

Inspection Date:

02/14/2015.

Client Name:

Kevin Slattery.

Client Email:

kevinpslattery@yahoo.com.

Inspector:

Frank van den Elzen, MA Lic.# 546.

Individuals Present:

Owner.

Outside Temperature:

JANITE

Outside Temperature

20F.

Ground Conditions:

Snow Covered.

Current Weather Conditions:

Overcast.

Past Day Weather Conditions:

Mostly Clear.

Inspection Conditions:

Fully Furnished Property, Snow Covered Conditions, Locked Front Bedroom.

Inspection Start Time:

12:00.

Inspection Finish Time:

1:40.

Inspection Type and Cost:

Single Family Home Inspection: \$425.00.

Radon Test:

None.

Other Services Provided:

None.

TOTAL AMOUNT DUE:

\$425.00 (Paid in Cash)

For a Home Maintenance Manual and other information for home buyers visit: http://www.tigerhomeinspection.com/en/info-for-home-buyers/resources/

Address: 35 Moreland Street, Somerville MA
Page 4 of 22



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Exterior						
General Comments:						
	The driv -An Hov gua con	ere is vewag vexte weve arante nplet	no a y and erior i r, du ee wl	and/or I foun re-ins ring p hen th efore	· limit datio pection rolon nis re a cer	eport are rated "NR" due to access limitations caused by snow, red access to roof, gutters, grading, exterior outlets, walkways, on. on at the inspector's convenience is part of this inspection, aged snow conditions and due to schedules, we can not inspection will take place. If you need your inspection retain date, it is advised to make arrangements with our office to me when snow cover is gone. In this case a re-inspection fee will
Roof System:			•			
Structure Type:	Pito	ched,	Low	Pitch	1.	
Surface Type:	Asp	bhalt	Shin	gles.		
How inspected:	Bin	ocula	ars, f	r. Wir	idow	(partially)
Roof Penetrations:	Chi	imne	y, Ve	nt St	ack, /	Attic Fans.
Condition of Roof Structure:	A	B ☑	C	NR □	. □	Evidence of rafter spread noted. Typical visual signs of rafter spread are bowing out walls. This condition generally occurs due to improper alterations to the roof framing. Consult contractor to further assess roof framing.
Condition of Roof Surface:			Ø		Ø	-Rear addition roof does not have proper pitch (less than 2/12) for asphalt shingle application. Area shows signs of prior leaking and has been covered with a tarp. Advise installation of a continuous roofing material like rubber roofing or rolled asphalt. -Condition of visual asphalt shingles is reflective of age, with signs of weathering and curling. Anticipate future roof upgrade. It appears the roof has multiple layers of asphalt shingles. It is advised to have no more than two layers of roofing. The roof will need to be stripped when re-roofing.
Condition of Exposed Flashings:			V		V	Monitor tar patched chimney and waste vent flashings and reseal or upgrade as needed. Water stains noted in vicinity of the chimney.
Exterior Chimneys (Flue	Line	ers i	not i	inclu	ıded	i <mark>)</mark> :
Condition of Masonry Chimney:			Ø		Ø	Location: Center Components: No Cricket, Cleanout or Weather Cap present.

Address: 35 Moreland Street, Somerville MA Page 5 of 22

How Inspected: Binoculars

anything within 10ft. Consult mason.

are present is not part of this inspection.

-Chimney is too short and should be at least 2ft taller than

-The condition of the flue liners or determining whether they



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- HIRE THE EYE OF THE TIGER™ NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Siding:						
Type and Condition:	A ☑	B □	C	NR □	D	Type: Vinyl.
Trim: Eaves/Soffits/Corne	erbo	ard/	Win	dow	,	
Type and Condition:	M					Type: Aluminum Wrap, Vinyl Trim, Wood Trim.
Gutters and Downspouts Type and Condition	: ☑					Type: Aluminum Gutters with Aluminum Downspouts.
Perimeter Drainage and Grading/Drainage Conditions:		ing: □		团		Grade not visible due to snow coverage.
Basement Windows: Condition:				Ø		No access to windows due to snow.
Exterior Faucets: Condition:				Ø		No access due to snow covered conditions.
Electric Service Entry: Type and Condition:	Ø			D		Type: Overhead-Weather Head/Drip Loop with Conduit Drop, No Exterior Meter Service Amperage: Appears 100 Amp.
Exterior Outlets: Condition:				Ø		No found. Limited access due to snow.
Right Stairs: Materials and Condition:	Ø					Materials: Wood.
Walkways: Type and Condition:				Ø		Type: Not DeterminedNo access due to snow covered conditions.
Driveways: <i>Type and Condition:</i>				Ø		Type: AsphaltNo access due to snow covered conditions.

TIGER HOME INSPECTION

Our Rating System Is As Follows:

- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
- D: Further consultation with a contractor is advised.

Additional Important Information:

- -We suggest that you verify the age of the roof with the selling party. Roofing material performance estimates relate to typical conditions, assuming proper installation and maintenance. The actual life of the roofing material can be influenced by external sources like weather extremes, internal attic conditions, roof ventilation, house orientation, conditions caused by trees and vegetation or mechanical damages. It is advised that reserves be set aside for repairs or eventual roof replacement. Advise regular inspection of your roof flashing.
- -Due to limited access to the flashing, the findings in this report only apply to the exposed flashing and/or accessible evidence of flashing failure.
- -The condition of the flue liners or determining whether they are present is not part of this inspection. It is recommended that you further investigate this component. Local regulations in some communities require the presence of a flue liner when using certain fuels. Consult your local authorities.
- -The condition and type of material underneath the exposed siding and trim wrap can not be ascertained during this inspection. These components are covered by a more recent finished surface. The ratings in this report apply to visible course of siding and trim wrap, and installation thereof.
- -To prevent water damage to roof, sheathing, walls, ceilings and structural members, gutters and down spouts must be kept clean and clear of debris. It is suggested that you periodically check to ensure that your gutter system works as intended.
- -The underside of decks and porches is not accessible at the time of this inspection. It is suggested to make it accessible to check for damage, rot, insect infestation and construction methods. The ratings herein apply to the visible components only.
- -Sheds are not part of this inspection.

Address: 35 Moreland Street, Somerville MA Page 7 of 22



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- HIRE THE EYE OF THE TIGERTM NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Basement										
General Comments:	spa	Limited access to structural members during inspection due to inaccessible crawl space, finished walls, furnishings, cluttered conditions, appliances and plumbing. Structural members are rated accordingly.								
Foundation:										
Type and Condition:	A	B □	C ☑	NR □	D v	Type: Fieldstone, Brick -Foundation is failing. Evidence of substantial foundation settlement observed. The two foundation side walls are bowing and leaning. This lateral movement has caused various joists to loose their end bearing. Advise further evaluation by foundation specialist or structural engineer. Anticipate installation of a new foundation -The rear addition is not on a proper foundation and is supported by an insufficient number of wood posts instead. Advise installation of a proper foundation.				
Floor: Type and Condition:	Ø					Type: Concrete.				
Crawl Space:										
Condition:			Ø		Ø	How Viewed: From Opening -Limited access into crawl space due to height limitations, storage and rubble. Insulation Type: None Floor Type: Soil Vapor Barrier: No vapor barrier presentConsider installing one. Ventilation and vapor barriers are necessary to control moisture levels. Ventilation: No crawl space ventilation presentAdvise introducing crawl ventilation. Installing louvered vent openings that can be opened during spring and summer and closed in the winter is advisedThere is insufficient support under the girder in the crawl space. Advise installing a support column on a proper footing to cut the girder span in half.				
Girder(s):						A :-				
Type and Condition:		Ø			Ø	Type: WoodMain support beam shows evidence of sagging. This has resulted in floor deflections throughout property.				



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

NR□	D M	Type: Steel Lally, Adjustable Jacks, Wood -Suggest replacing wood posts and adjustable jacks with steel lally columns on proper footings. Timbers are subject to shrinkage and deterioration and adjustable jacks are considered a temporary support.					
\square		Type: Wood.					
\square		Floor Type: Wood Plank.					
	Ø	Type: WoodInsufficient end bearing observed. The joist end bearing has been affected by lateral foundation movement. The joist tails are pulling away from the sill pockets. See Foundation above. Consult contractor for evaluation and repair.					
i):							
		Type: Brick Components: No cleanout in placeConsult mason to parge spalling masonry chimney. Spalling is deterioration/erosion of the brick surface.					
\square		Type: None Present.					
Evidence of water penetration and dampness noted at time of inspection. Efflorescence observed on foundation walls. The source and amount of water penetration may not be observable at the time of inspection. Sump Pump: Sump pump in place. -Installation of sump pump system is not to professional standards. Correct sump pump that is improperly discharging into town sewer. Also observed improvised sump and no check valve. French Drain: Not Present. Dehumidifier: None Observed.							
	k valv n: Not	k valve. <i>n</i> : Not Pres					

Addition Important Information:

-A separate Wood Boring Insect report is provided with your inspection, either on site or by mail. Please review and follow through on directions as needed.

-Examination of structural members, wiring, piping, etc., cannot be conducted in full due to inaccessible crawl space areas. No destructive probing or removal of permanent or non-permanent partitions or flooring is performed.



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Plumbing System

Supply Plumbing Inforn	nation	:						
Water Service:		The water source is municipal. Verified by observation. Shut Off Location: The main shut off valve is located in basement, at front right.						
Waste Plumbing Inform	ation:							
Waste Service:	The	was	te sy	stem	is m	unicipal. Verified by observation.		
Accessible Water Supp	ly Line	es:						
Type and Condition:	A	B	C	NR □	D ☑	Type: Copper -Aged valves appear corroded and caked. Suggest upgrade to ball valves. Note: Mineralization, corrosion and general wear may cause leaking when operating aged valvesCorrosion noted due to flux not wiped off solder joints. Clean pipes joints to halt decay.		
Accessible Drain/Waste	Lines	3:						
Type and Condition:			Ø		☑	Type: Cast Iron, PVC -Anticipate upgrades and repairs of worn cast iron waste lines Observed corrosion, evidence of pitting, rust blisters and signs of weepingSump pump is improperly discharging into waste system. No trap present.		
Main Vent Stack:								
Condition:				Ø		Waste venting system is sealed inside walls and not accessible for inspection.		
Water Heater:								
Type and Condition:		Ø				Manufacturer: GE System Type: Individual tank water heater. Fuel Type: Natural Gas Tank Size: 30 gallon System Components: P&T Relief Valve, Vacuum Breaker Thimble: No thimble in place at chimney entry pointAdd proper discharge extension to P&T valve. This extension should terminate 6" to 12" above floor surface.		
Washer/Dryer Connecti	ons:							
Washer Connections:		Ø				Add cover to washer outlet.		
Dryer Connections:			V			-Plastic dryer duct present. Advise upgrade to a rigid, or		

semi-rigid metal dryer duct.

-Clean out lint and maintain your dryer and dryer duct

periodically to ensure safe operation and proper performance.

TIGER HOME INSPECTION

Our Rating System Is As Follows:

- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Additional Important Information:

- -Operation of main valves, individual fixture shut offs and other valves is beyond the scope of a home inspection.
- -The type of sewage disposal system as noted above is determined by information provided by either seller, broker or client. It is not a determination of its actual type, design or condition. An optional inspection report is available to offer an opinion of the systems type, effectiveness and condition.
- -Supply and waste line information is for reference purposes only. Tiger recommends you confirm this information with the municipality.
- -The warranty period for water heaters vary from manufacturer to manufacturer; this should not be confused with the actual life expectancy which could be more or less. Please refer to the warranty for the extent and terms, if any.
- -The laundry appliances are not operated during inspection. Observations are for identification purposes only, not determination of proper operation or termination.

Address: 35 Moreland Street, Somerville MA Page 11 of 22

TIGER HOME INSPECTION

Our Rating System Is As Follows:

- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Electric System

System imormation.										
Supply Voltage:	120	/240	Volts	S.						
Main Disconnect Amperage:	100	100 Ampere.								
Service Wire Size and Type:	ΑW	AWG #2, AL.								
Over-Current Devices Type:	Circ	Circuit Breakers, GFCI Breaker.								
Panel Location:	Bas	eme	nt.							
Over-Current Devices Off:	Obs	Observed GFCI circuit in the "off" position.								
CU/AL Compatible:	Over-current protection devices are CU/AL rated.									
Anti-Oxidant Present:	No	anti-d	oxida	nt ge	l pres	sent on aluminum wire connections inside panel.				
Accessible Wiring:										
	A	В	С	NR	D					
Type and Condition:		Ø	Ö		\(\overline{\pi}\)	Type: Copper, Romex, BX Cable, Stranded Aluminum -Installation of wiring is not up to professional standards. Observed loose later installed wiring. Consult electrician for clean upExpand electric system. Add more outlets and circuits to bring electric up to current standard.				
Service Panel:										
Condition:		図			Ø	-Consult electrician to eliminate double tapped breakers. Multiple wires/circuits are connected to a single lug on a circuit breakerNo anti-oxidant present on aluminum wire tips and lugs at main disconnect. Consult electrician to rectify as neededThe breakers are not labeled as to the circuits or appliances controlled. Suggest proper labeling of panel.				
Ground Terminal Bar: Condition:	Ø									
Grounding/Bonding:										
Condition:		V			Ø	The system ground is not bonded on both sides of the water meter. Have electrician install a system ground jumper to house side of water meter.				
GFCI Breakers:										
Condition:			Ø		Ø	Number of GFCI breakers in place at the panel: 1 -The tripped GFCI breaker in the panel failed to reset. This indicates a ground fault (GFCI may have tripped due to a we and snow covered exterior outlet). Consult electrician for further evaluation.				
AFCI Breakers:										
Condition:				$ \overline{\mathbf{V}} $		No AFCI breakers present in the panel.				



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required

NR: Not Inspected, not readily accessible or not present. No rating.

D: Further consultation with a contractor is advised.

Junction Box Covers:						
	Α	В	C	NR	D	
Condition:	V					
Switch/Outlet Covers:						
Condition:			Ø			Correct missing outlet covers in bedroom, 2nd floor bathroom and laundry area.
Additional Important Inf	orma	tion	:			
	reg -Th	ulatione pre	ons a esent	nd mo main	ortga ove	de electric service can be influenced by client's need, local ge lending institutions. r-current protection capacity is not always an indication of its
	-Oı cor	nce o ntact.	r twic Reg	ce a y gular t	ear f estin	Insult with an electrician for Amperage verification. Ilip circuit breakers off and on to maintain good mechanical Ilip of the GFCI protected outlets/circuits is advised per Inendation.
	Lig -Sr	ht sw noke	itche and	es and CO d	l ligh etect	conditions allow for only random testing of electrical outlets. t fixtures are not part of this inspection and are not rated. ors should be present and approved by the local fire dept. prior



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Central Heating and Cooling

General Information:										
		GAS LEAK! Gas odor noted during inspection. Advise immediate consultation with gas company.								
System Location:	Bas	seme	nt.							
Fuel Source:	Natural Gas.									
Thermostat(s):										
` '	Α	В	С	NR	D					
Condition:	Ø					Location: Living Room.				
Exposed Flue/Damper:										
Type and Condition:	Ø					Flue Material: Galvanized Thimble: No thimble in place at chimney entry point. Consult a heating technician or local authorities regarding regulations and requirements.				
Burner/Gun:										
Condition:			☑		Ø	-There are no signs of recent servicing. Burner is dirty and produces a yellow flame. Advise servicing of heat plantAn annual tune up of your gas fired heat plant is advised.				
Boiler:						•				
Type and Condition:		团			Ø	Boiler Type: Gravity Hot Water Boiler Components Include: Expansion Tank, Auto Feed Valve, Pressure Relief Valve System Pressure: Not Determined System Temperature: Not Determined -Consider upgrade of fully depeciated, outdated and slow gravity hot water boiler system.				
Circulator Pump(s):										
Condition:				Ø		Number of Circulator Pumps: 0.				
Accessible Distribution I	Pipes	s/Plu	ımb	ing:						
Type and Condition:		Ø				Distribution Piping Type: Black Iron				
Cooling System (Ducted	Syst	tems	s):							
Type and Condition:				\square		Type: Not Present.				



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
- D: Further consultation with a contractor is advised.

Additional Important Information:

-This report indicates the condition of the heat plant on the day of the inspection without regard to life expectancy. We suggest that you obtain a major service policy for the heat plant from a dealer or HVAC contractor, which should include annual servicing, adjustments, efficiency testing, warranty and emergency service.
-Relief valves, valves, gauges, control components, switches, and other safety devices can not be tested. They are listed on the report to denote that they were observed in place in the system.

-Identification of asbestos containing materials is beyond the scope of a home inspection. Further evaluation by a licensed specialist is suggested if potentially asbestos containing materials were noted at accessible areas during your inspection.

-Gas piping and meters are not part of this inspection. Consult a licensed contractor or gas provider for evaluation.

Address: 35 Moreland Street, Somerville MA Page 15 of 22



Kitchen:

Our Rating System Is As Follows:

- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- HIRE THE EYE OF THE TIGERTM NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Kitchen and Interior Accessories

	Α	В	C	NR	D	
Sink:	V					Temp: 120F.
Counters:		Ø				Wear and tear noted.
Cabinets:		\square				Wear and tear noted on cabinets.
Ceiling:	Ø					Type: Metal.
Walls:	Ø					Type: Paneling.
Floor:		Ø				Type: VinylSubstandard vinyl floor tile installation noted.
Windows:		Ø				Suggest upgrade or refurbishing of worn window.
Electrical Outlets:			Ø		Ø	Advise upgrade to GFCI protected kitchen counter outlets. All counter outlets and all outlets within 6 ft. of a wet location need to be GFCI protected.
Heat Source:				Ø		Type: None.
Appliances:						
Stove:		Ø			Ø	Fuel Type: Gas -Stove has not been secured as required by manufacturer's installation instructions. Properly secure stove using an anti tip bracket.
Ventilation:						Note: The exhaust vent is a re-circulating filter type.
Dishwasher:		V				Unit is not properly secured. Correct as needed.
Waste Disposal:						Not Present.



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Into	rior	Acce	een	riae:
шк	пог	ALLE	35 U	Les.

A	В	C	NR	D	
V					
V					
		V			Properly secure loose handrail.
	Ø			Ø	The handrail is incomplete and does not extend covering the full path of the stairs. Correct as needed.
	Ø			☑	-Correct reversed polarity at hallway outletWater damaged ceiling area observed at side entry hallway. Further investigation and repair is recommended.
			\square		No skylights present.
			Ø		No fireplace present.
	Ø				

Additional Important Information:

-Unless otherwise noted, all appliances listed are working on the day of the inspection. Tiger Home Inspection, Inc. does not represent a guarantee or warranty of the continuous operation of the appliances. Self-cleaning features, oven convection systems, timers, clocks, thermostats, gasket or seal performance and cosmetic blemishes are not part of this inspection report. Fridges, microwaves, laundry machines, dryers, trash compactors and central vacuum systems are not included.



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Bathrooms

Half Bath:

	A	В	C	NR	D	
Sink:	\square					<i>Temp</i> : 120F.
Toilet:			V			Cracked flush tank lid observed. Suggest upgrade.
Ceiling:	Ø					Type: Gypsum.
Walls:	☑					Type: Paneling.
Floor:						Type: Tile.
Windows:			Y		V	Correct broken/disconnected window springs.
Door(s):					П	
Electrical Outlet(s):			\checkmark		Ø	No bathroom outlet present. Advise installing GFCI outlet.
Ventilation Fan:				\square		Not Present.
Heat Source:				\mathbf{V}		Type: None.
Main Bathroom:						
Sink:		V			Ø	Temp: 120F -Suggest upgrade of substandard under-sink flex plumbing. Install rigid lineAdd sink stopper as needed.
Toilet:	☑					-Add Silik Stopper as needed.
Tub/Shower:			Ø		Ø	Type: Tub/Shower Combination -Advise upgrade of leaking, outdated valves. The valve stems are loose. A modern anti-scald mixing valve is preferable.
Tub/Shower Walls:						Type: Fiberglass.
Ceiling:						Type: Gypsum,
Walls:	\checkmark					Type: Paneling.
Floor:						Type: Marble Tile.
Windows:			Ø		Ø	-Upgrade panes with broken thermal seals. Foggy deposit trapped between panes noted. Correct missing screen.
Door(s):	V					
Electrical Outlet(s):			1		Ø	Correct reversed polarity at outlet and correct missing outlet cover. Advise upgrade to GFCI protected bathroom outlet. Ground Fault Circuit Interrupter protected outlets are advised wherever a user may come in contact with water.
Ventilation Fan:				团		Not Present.
Heat Source:	171	П	П	П	П	Type: Radiator Temp: 120F

Additional Important Information:

-Inspection is limited to visual conditions at tub/shower wall. Conditions behind finished surfaces are not accessible (NR). Maintain all caulk and grout seals to prevent negative effects of moisture.



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Interior - Rooms

General Comments:

-Insufficient number of outlets present throughout property. Suggest adding more outlets to bring home up to current standard. Observed excessive use of extension cords. This is not advised.

-No access into front bedroom on 2nd floor. Room was locked during inspection and not part of this inspection.

Living and Dining Room:

	Α	В	C	NR	D	
Ceiling:	V					Type: Gypsum, Suspended.
Walls:	\square					Type: Gypsum, Paneling.
Floor:		$ \overline{\mathbf{V}} $				Type: Wood.
Windows:		Ø				Correct missing window screens.
Door(s):		Ø				Correct not latching French doors.
Electrical Outlets:		Ø			Ø	 Insufficient number of outlets present. Suggest adding more outlets to bring rooms up to current standard. Advise upgrade of painted over outlets.
Heat Source:		团			Ø	Type: Radiators, Temp: 110F, None -No temperature increase observed at dining room radiator. Radiator may have been shut off. Further investigation is recommended.
1st Floor Bedroom:						
Ceiling:		团			Ø	Type: Gypsum -Water stained ceiling areas observed. There is a blue tarp present on the roof at this location. See Exterior section of this report under Roof. Further evaluation may reveal concealed damage and other related water penetration issues.
Walls:	☑					Type: Paneling.
Floor:	\square					Type: Laminate.
Windows:		☑			Ø	-Upgrade damaged window crankCorrect missing window screens.
Door(s):						
Electrical Outlets:	Ø					
Heat Source:						Type: Radiator, Temp: 110F.



- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- HIRE THE EYE OF THE TIGER™ NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

2nd Floor Bedroom (Rear Only)	2nd	Floor	Bedroom	(Rear	Only)
-------------------------------	-----	-------	---------	-------	-------

	A	b	C	NK	ט	
Ceiling:		Ø			Ø	Type: Gypsum -Water stained ceiling areas observed near chimney. Furthe investigation is recommended.
Walls:	Ø					Type: Paneling.
Floor:	◩					Type: Wood.
Windows:		Ø				Correct missing window screen.
Door(s):	Ø					
Electrical Outlets:			Ø			Have electrician bring outlets up to current standard. Add more outlets, correct reversed polarity outlets and correct loose outlet that is falling out of the wall.
Heat Source:			Ø		Ø	<i>Type</i> : Radiator, <i>Temp</i> : 105F -Repair leaking radiator valve.

Additional Important Information:

- -Cosmetic defects such as: worn carpets, fading or peeling paint, and holes and blemishes on walls, ceilings, flooring, doors and trim are not reported.
- -Hairline cracks are not unusual on interior wall and ceiling surfaces, due to minor shrinkage and settlement.
- -Due to the nature of the deficiency, insulated double-pane windows and skylights may have broken thermal seals that may not be detected.



- A: Item is functioning as originally intended.
- B. This item is not functioning as originally intended. Maintenance, repair and upgrade required.
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- HIRE THE EYE OF THE TIGER™ NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Attic - Ventilation - Insulation

General Comments:

No attic scuttle found during inspection. No access into overhead and eave attic

	cavities. This prevents inspection of structural members, insulation, ventilation and evidence of water penetration. Various items are rated accordingly.									
Attic Access:										
	A	В	C	NR	D					
Type and Condition:				\square		Type: Not Determined.				
Structural Components:										
Roof Framing:		团				Support Type: Wood RaftersEvidence of rafter spread noted. Typical visual signs of rafter spread are bowing out walls. This condition generally occurs due to improper alterations to the roof framing. Consult contractor to further assess roof framing.				
Roof Backing:				\square		Type: Wood Planks.				
Ceiling Joists:				Ø		Type: Wood Timbers.				
Chimneys (flue liners not	incl	lude	d):							
Type and Condition:			Ĺ	Ø		Type: Masonry -No access to chimney due to fully finished construction,				
Insulation (attic only):										
Type and Condition:				M		Type: Not Determined Depth: Not Determined.				
Ventilation:										
Type and Condition:				团		Type: Two Attic Fans - The existing system does not supply sufficient ventilation of the attic cavity. Suggest installing a ridge and soffit attic ventilation system when re-roofing. A proper roof ventilation system will prevent moisture build up, reduces ice damming and will prolong the life of your roof and roof backing.				
Water Penetration:										
Evidence of Water Penetration:	chir the	mney se ok	, 1st serv	floor ations	bedr s and	water penetration on ceilings in 2nd floor bedroom near com and side entry. Consult contractor for further evaluation of I repair as needed. See Exterior section of this report under				

TIGER HOME INSPECTION

Our Rating System Is As Follows:

- A: Item is functioning as originally intended.
- B: This item is not functioning as originally intended. Maintenance, repair and upgrade required,
- C: This item is not functioning at time of inspection. Maintenance, repair and upgrade required
- NR: Not Inspected, not readily accessible or not present. No rating.
 - D: Further consultation with a contractor is advised.

Additional Important Information:

- -During this inspection we can not determine whether noted water penetration evidence has been addressed. Check for history with selling party. Monitor and repair as needed.
- -Evidence of discoloration, high moisture and/or water penetration observed. The source/cause and the amount of water penetration may not always be detectable. Tiger recommends you consult the owner or a contractor for a historical perspective regarding this observation. These conditions can be associated with environmental issues. You should consult a qualified specialist if you have any concerns.
- -Presence of insulation in the wall cavities can not be determined during this inspection. Be aware that prior to the adoption of federal, state and local codes in the mid-70s, homes were typically built with minimum insulation. Today's home owner, faced with rising energy costs, should consider the return investment of insulation upgrades.
- -Attic ventilation is an important factor in the life expectancy of roof sheathing and shingles. Provide maximum air flow to minimize heat buildup in summer and condensation in winter. Do not cover or block vents.

State-Recommended Questions A to K

The Commonwealth of Massachusetts Home Inspection Regulations 266 CMR, Section 6.03 (4) requires the inspector to notify his/her client that answers to the following questions should be ascertained from the seller and/or the seller's representative. It should be understood that the answers may not be readily observable by the inspector at the time of the inspection, and that there is no legal obligation by the seller and/or the seller's representative to answer them. The Massachusetts Home Inspection Regulation can be viewed at: www.mass.gov/dpl/boards/hi

To the Best of Your Knowledge as the Seller and/or Seller's Representative:

(a)	Does the dwelling have a history of seepage, dampness, and/or water penetration into the basement
	and/or under-floor crawl space? If so, please explain.
(b)	Has a sump pump ever been installed or used in the basement/under-floor crawl space?
(c)	Do you use any type of dehumidification in any part of the dwelling?
(d)	Are you aware of any mold and/or air quality issues in the dwelling?
(e)	Is the dwelling on a private sewage system?
	1. If the waste system is private, has a Title V inspection been completed, and is the completed
	Title V Report available for review?
	2. Has the dwelling ever been inspected and/or treated for insect infestation?
	a. If so, when?
	b. What were the chemicals used?
(f)	Has the dwelling ever been tested for radon gas and/or lead paint?
	1. If so when?
	2. What were the results?
(g)	Has the dwelling ever been inspected by an inspector?
	1. If so, when?
	2. Were any problems noted?
	3. Is a copy of the inspection report available?
(h)	Are the seller/seller's representative aware of any structural, mechanical, electrical or other material
	defects that may exist on the property?
(i)	Has there ever been a fire in the dwelling?
	1. If so, when?
	2. What areas were involved?
	3. What chemical cleaners, if any, were used for cleanup?
(j)	Has there ever been a hazardous waste spill on the property?
(k)	Is there an underground storage tank on the property?