## **Existing Facade**

BLADE SIGN IS CLUNKY. UNCLEAR WHICH IS PRIMARY, FASIKA OR BEER?


BRICK INFILL DOES NOT MATCH FRIEZE **BRICK** 

AWNINGS LOOK DATED; FORM IS OUT OF CONTEXT

> RESTAURANT NAME IS VERY LOW COMPARED TO NEIGHBORING STORES

BARRED PEEPHOLE WINDOWS ARE UNINVITING, PARTICULARLY FOR AN UNUSUAL CUISINE.

POINT OF ENTRY IS CONFUSING. SECOND ENTRY IS UNNECESARY



- LACK OF TRANSPARENCY IS FORBIDDING
- LACK OF COLOR
- ALMOST NOTHING IS IDENTIFIABLE WITH ETHIOPIAN CUISINE



## Scheme 3a

REMOVE EXISTING BLADE

> MODERN SIGN LIGHTS

1" ALUMINUM DIMENSIONAL ICON

1" ALUMINUM CHANNEL LETTERS PINNED TO FACADE

PAINTED METAL **BLADE SIGN WITH** RAISED LETTERS

SUNBRELLA AWNING ON ALUMINUM TUBE STRUCTURE

INFILL LEFT ENTRANCE WITH REUSED BRICK AND REPLACE **EXISTING WINDOW WITH** OPERABLE GLAZING BAND

> REMOVE GRILLE AND REPLACE WINDOW; ADD CUSTOM VINYL GRAPHIC

> > REPLACE ENTRY DOOR BEYOND





## Scheme 3b

REMOVE EXISTING BLADE

> MODERN SIGN LIGHTS

1" ALUMINUM DIMENSIONAL ICON

1" ALUMINUM CHANNEL LETTERS PINNED TO FACADE


PAINTED METAL BLADE SIGN WITH RAISED LETTERS

SUNBRELLA AWNING ON ALUMINUM TUBE STRUCTURE

INFILL LEFT ENTRANCE WITH REUSED BRICK AND REPLACE EXISTING WINDOW WITH OPERABLE GLAZING BAND


> REMOVE GRILLE AND REPLACE WINDOW; ADD CUSTOM VINYL GRAPHIC

REPLACE ENTRY DOOR AND BRICK WING WALLS BEYOND WITH ALUMINUM AND GLASS STOREFRONT SYSTEM (3-SIDES)







04.22.10





2 Level 1 Demo 1/8" = 1'-0"







Storefront Wall Section
3/8" = 1'-0"

DEREKRUBINOEE ARCHITECT

11 Sherwood Street #2, Routindale, MA 02131-3729 617-504-2599 drebinof@dereienbinoff.com

Proposed Storefront Sections

Fasika Ethiopian Restaurant

Fasika Ethiopian Restaurar
 147 Broadway
 Somerville, MA 02145

 IOB #:
 1006

 SCALE:
 As indicated

 DATE:
 5/24/2010

 DWN BY:
 Author

 CROSS REF:
 2ROSS REF:

SKD-2